

Limited Operational
Impact Study
For
Generation Interconnection
Request
GEN-2008-018

SPP Generation Interconnection

(#GEN-2008-018)

September 2011

## **Executive Summary**

<OMITTED TEXT> (Customer) has requested a Limited Operation Impact Study under the Southwest Power Pool Open Access Transmission Tariff (OATT) for interconnection of 405 MW of wind generation within the balancing authority of Southwestern Public Service Company (SPS) in Finney County, Kansas. Customer has requested this Limited Operation Interconnection Study (LOIS) to determine the impacts of interconnecting its generating facility to the transmission system before all required Network Upgrades identified in the ICS-2008-001-4 Impact Re-Study can be placed into service. Limited Operation Studies are conducted under GIA Section 5.9.

This study assumed that only the higher queued projects identified in Table 7 of this study might go into service before the completion of all Network Upgrades identified in ICS-2008-001-4. If any additional generation projects not identified in Table 7 but with queue priority equal to or over GEN-2008-018, those projects listed in Table 8, request to go into commercial operation before all Network Upgrades identified through the ICS-2008-001-4 study process as required, then this study must be conducted again to determine whether sufficient limited interconnection capacity exists to interconnect the GEN-2008-018 interconnection request in addition to all higher priority requests in operation or pending operation.

A power flow analysis shows that the Customer's wind facility will be limited to 369 MW of interconnection capacity. This capacity is not available until both the Balanced Portfolio Project; Spearville – Post Rock (Knoll) 345kV, and Hitchland – Moore County 230kV projects are in-service. Powerflow analysis was based on both summer and winter peak conditions and light loading cases.

The wind generation facility was studied as a 369 MW request with two hundred forty-six (246) G.E. 1.5 MW wind turbine generators. This Impact study addresses the dynamic stability effects of interconnecting the plant to the rest of the SPS transmission system for the system condition as it will be on December 31, 2012. Two seasonal base cases were used in the study to analyze the stability impacts of the proposed generation facility. The cases studied were modified 2011 summer peak and 2011 winter peak cases that were adjusted to reflect system conditions at the requested in-service date. Each case was modified to include prior queued projects that are listed in the body of the report. Fifty-five (55) contingencies were identified for use in this study. The G.E. 1.5 MW wind turbines were modeled using information provided by the Customer.

Nothing in this study should be construed as a guarantee of transmission service. If the customer wishes to sell power from the facility, a separate request for transmission service shall be requested on Southwest Power Pool's OASIS by the Customer.

#### 1.0 Introduction

<OMITTED TEXT> (Customer) has requested an Impact Study under the Southwest Power Pool Open Access Transmission Tariff (OATT) for interconnection of 405 MW of wind generation within the balancing authority of Southwestern Public Service Company (SPS) in Finney County, Kansas. Customer has requested this Limited Operation Interconnection Study (LOIS) to determine the impacts of interconnecting its generating facility to the transmission system before all required Network Upgrades identified in the ICS-2008-001-4 Impact Re-Study can be placed into service. Limited Operation Studies are conducted under GIA Section 5.9.

This Impact study addresses the dynamic stability effects of interconnecting the plant to the rest of the SPS transmission system for the system condition as it will be on December 31, 2012. The wind generation facility was studied as a 369 MW request with two hundred forty-six (246) G.E. 1.5 MW wind turbine generators. Two seasonal base cases were used in the study to analyze the stability impacts of the proposed generation facility. The cases studied were modified versions of the 2011 summer peak and 2011 winter peak to reflect the system conditions at the requested inservice date. Each case was modified to include prior queued projects that are listed in the body of the report. Fifty-five (55) contingencies were identified for this study.

#### 2.0 Purpose

The purpose of this Limited Operation Interconnection Study (LOIS) is to evaluate the impact of the proposed interconnection on the reliability of the Transmission System. The LOIS considers the Base Case as well as all Generating Facilities (and with respect to (b) below, any identified Network Upgrades associated with such higher queued interconnection) that, on the date the LOIS is commenced:

- a) are directly interconnected to the Transmission System;
- b) are interconnected to Affected Systems and may have an impact on the Interconnection Request:
- c) have a pending higher queued Interconnection Request to interconnect to the Transmission System listed in Table 7; or
- have no Queue Position but have executed an LGIA or requested that an unexecuted LGIA be filed with FERC.

Any changes to these assumptions, for example, one or more of the previously queued projects not included in this study signing an interconnection agreement, may require a re-study of this request at the expense of the customer.

Nothing in this System Impact Study constitutes a request for transmission service or confers upon the Interconnection Customer any right to receive transmission service.

#### 3.0 Facilities

#### 3.1 Generating Facility

The project was modeled as a pair of equivalent wind turbine generators each of 184.5 MW output (369 MW total). The wind turbines are each connected to 0.69/34.5KV generator step-up units (GSU). The high side of each GSU is connected to a 34.5/345kV substation transformer. A 345kV transmission line connects the Customer's substation transformers to the POI. This equivalent model representation is illustrated in Figure 2.

# 3.2 Interconnection Facility

The Point of Interconnection will be at the Transmission Owners Finney 345kV transmission line. Figure 1 shows a one-line illustration of the facility and the proposed POI. Figure 2 shows a one-line bus interconnection of the Point of Interconnection.

Cost to interconnect on a Limited basis is estimated at \$2,564,167.




Figure 1: GEN-2008-018 Facility and Proposed Interconnection Configuration




Figure 2: GEN-2008-018 Bus Interconnection

#### 4.0 Power Flow Analysis

A powerflow analysis was conducted for the Interconnection Customer's facility using a modified version of the 2011 spring, 2012 summer, and 2012 winter seasonal models. The output of the Interconnection Customer's facility was offset in the model by a reduction in output of existing online SPP generation. This method allows the request to be studied as an Energy Resource (ERIS) Interconnection Request. This analysis was conducted assuming that previous queued requests listed in Table 7 were in-service.

The Southwest Power Pool (SPP) Criteria states that:

"The transmission system of the SPP region shall be planned and constructed so that the contingencies as set forth in the Criteria will meet the applicable NERC Reliability Standards for transmission planning. All MDWG power flow models shall be tested to verify compliance with the System Performance Standards from NERC Table 1 – Category A."

The ACCC function of PSS/E was used to simulate single contingencies in portions of or all of the control area of SPS and other control areas within SPP and the resulting data analyzed. This satisfies the "more probable" contingency testing criteria mandated by NERC and the SPP criteria.

Higher queued projects listed in Table 8 were not modeled as in service. If any of these come in service, this study will need to be performed again to determine if any limited interconnection service is available.

The ACCC analysis indicates that the Customer's project can interconnect 369 MW into the SPS transmission system before injection constraints were identified. This analysis was studied with both the Balanced Portfolio Project; Spearville – Post Rock 345kV, and Hitchland – Moore County 230kV projects in-service.

Sensitivity analyses were conducted which included certain higher queued projects listed in Table 8. These projects included:

- GEN-2004-014
- GEN-2006-022
- GEN-2006-006

The sensitivities were sequentially added to the original analysis to determine their effect on available interconnection. With the inclusion of GEN-2004-014, the available interconnection remained at 369 MW. The additional inclusion of GEN-2006-022 did not further reduce the available interconnection. The final studied additional inclusion of GEN-2006-006 reduced the available interconnection to 289.5 MW.

These ACCC result summaries are shown below in the following tables.

# Table 1: ACCC Analysis with GEN-2008-018 interconnection at 405 MW

SEASON	SOURCE	DIRECTION	MONTCOMMONNAME	RATEA	RATEB	TDF	TC%LOADING	MW Available	CONTNAME
11G	G08_018		NCONV			0.69811		369*	'FINNEY SWITCHING STATION - HOLCOMB 345KV CKT 1'

<sup>\*</sup>Generator Power was reduced until a powerflow solution was reached.

## Table 2: ACCC Analysis with GEN-2008-018 interconnection at 369 MW

SEASON	SOURCE	DIRECTION	MONTCOMMONNAME	RATEA	RATEB	TDF	TC%LOADING	MW Available	CONTNAME
			None						

## Table 3: ACCC Analysis with GEN-2008-018 interconnection at 369 MW and GEN-2004-014

SEASON	SOURCE	DIRECTION	MONTCOMMONNAME	RATEA	RATEB	TDF	TC%LOADING	MW Available	CONTNAME
			None						

## Table 4: ACCC Analysis with GEN-2008-018 interconnection at 369 MW, GEN-2004-014, and GEN-2006-022

SEASON	SOURCE	DIRECTION	MONTCOMMONNAME	RATEA	RATEB	TDF	TC%LOADING	MW Available	CONTNAME
			None						

# Table 5: ACCC Analysis with GEN-2008-018 interconnection at 369 MW, GEN-2004-014, GEN-2006-006, and GEN-2006-022

SEASON	SOURCE	DIRECTION	MONTCOMMONNAME	RATEA	RATEB	TDF	TC%LOADING	MW Available	CONTNAME
11G	G08_018	'TO->FROM'	'CIRCLE - MULLERGREN 230KV CKT 1'	319	319	0.20935	101.9297	350.503	'Hitchland Interchange - STEVENSCO 345.00 345KV CKT 1'
11G	G08_018	'TO->FROM'	'CIRCLE - MULLERGREN 230KV CKT 1'	319	319	0.20935	101.8631	351.1759	'FINNEY SWITCHING STATION - STEVENSCO 345.00 345KV CKT 1'
11G	G08_018	'TO->FROM'	'MULLERGREN - SPEARVILLE 230KV CKT 1'	330.3	355.3	0.21616	108.1912	289.5637	'POSTROCK7 345.00 - SPEARVILLE 345KV CKT 1'
11G	G08_018	'TO->FROM'	'MULLERGREN - SPEARVILLE 230KV CKT 1'	330.3	355.3	0.21616	108.1737	289.7356	'POSTROCK7 345.00 (POSTROCK T1) 345/230/13.8KV TRANSFORMER CKT 1'

## 5.0 Stability Analysis

# 5.1 Contingencies Simulated

Fifty-five (55) contingencies were considered for the transient stability simulations. These contingencies included three phase faults and single phase line faults at locations defined by SPP. Single-phase line faults were simulated by applying a fault impedance to the positive sequence network at the fault location to represent the effect of the negative and zero sequence networks on the positive sequence network. The fault impedance was computed to give a positive sequence voltage at the specified fault location of approximately 60% of pre-fault voltage. This method is in agreement with SPP current practice.

The faults that were defined and simulated are listed in Table 6 below.

**Table 6: Contingencies Evaluated** 

Cont. No.	Cont. Name	Description
1.	FLT01-3PH	3 phase fault on the Woodward (515375) to Tatonga (515407) 345kV line, near Woodward. a. Apply fault at the Woodward 345kV bus. b. Clear fault after 5 cycles by tripping the faulted line. c. Wait 20 cycles, and then re-close the line in (b) back into the fault. d. Leave fault on for 5 cycles, then trip the line in (b) and remove fault.
2.	FLT02-1PH	Single phase fault and sequence like previous
3.	FLT03-3PH	3 phase fault on the Finney (523853) to Hitchland (523097) 345kV line, near Finney.  a. Apply fault at the Finney 345kV bus.  b. Clear fault after 5 cycles by tripping the faulted line.  c. Wait 20 cycles, and then re-close the line in (b) back into the fault.  d. Leave fault on for 5 cycles, then trip the line in (b) and remove fault.
4.	FLT04-1PH	Single phase fault and sequence like previous
5.	FLT05-3PH	3 phase fault on one of the Finney (523853) to Holcomb (531449) 345kV lines, near Finney.  a. Apply fault at the Finney 345kV bus.  b. Clear fault after 5 cycles by tripping the faulted line.  c. Wait 20 cycles, and then re-close the line in (b) back into the fault.  d. Leave fault on for 5 cycles, then trip the line in (b) and remove fault.
6.	FLT06-1PH	Single phase fault and sequence like previous
7.	FLT07-3PH	3 phase fault on the Finney (523853) to Lamar (599950) 345kV line, near Finney.  a. Apply fault at Finney 345kV bus.  b. Clear fault after 5 cycles by tripping the faulted line.  c. Wait 20 cycles, and then re-close the line in (b) back into the fault.  d. Leave fault on for 5 cycles, then trip the line in (b) and remove fault.
8.	FLT08-1PH	Single phase fault and sequence like previous
9.	FLT09-3PH	3 phase fault on the Knoll (530558) to Post Rock (530584) 230kV line, near Knoll. a. Apply fault at the Knoll 230kV bus. b. Clear fault after 5 cycles by tripping the faulted line. c. Wait 20 cycles, and then re-close the line in (b) back into the fault. d. Leave fault on for 5 cycles, then trip the line in (b) and remove fault.

Cont. No.	Cont. Name	Description
10.	FLT10-1PH	Single phase fault and sequence like previous
11.	FLT11-3PH	3 phase fault on the Knoll (530558) to Smoky Hills (530592) 230kV line, near Knoll. a. Apply fault at the Knoll 230kV bus. b. Clear fault after 5 cycles by tripping the faulted line. c. Wait 20 cycles, and then re-close the line in (b) back into the fault. d. Leave fault on for 5 cycles, then trip the line in (b) and remove fault.
12.	FLT12-1PH	Single phase fault and sequence like previous
13.	FLT13-3PH	3 phase fault on the GEN-2007-040 (531000) to Holcomb (531449) 345kV line, near GEN-2007-040. a. Apply fault at the GEN-2007-040 345kV bus. b. Clear fault after 5 cycles by tripping the faulted line. c. Wait 20 cycles, and then re-close the line in (b) back into the fault. d. Leave fault on for 5 cycles, then trip the line in (b) and remove fault.
14.	FLT14-1PH	Single phase fault and sequence like previous
15.	FLT15-3PH	3 phase fault on the GEN-2007-040 (531000) to Spearville (531469) 345kV line, near GEN-2007-040. a. Apply fault at the GEN-2007-040 345kV bus. b. Clear fault after 5 cycles by tripping the faulted line. c. Wait 20 cycles, and then re-close the line in (b) back into the fault. d. Leave fault on for 5 cycles, then trip the line in (b) and remove fault.
16.	FLT16-1PH	Single phase fault and sequence like previous
17.	FLT17-3PH	3 phase fault on the Pioneer (531391) to Hickock (531378) 115kV line, near Pioneer.  a. Apply fault at the Pioneer 115kV bus.  b. Clear fault after 5 cycles by tripping the faulted line.  c. Wait 20 cycles, and then re-close the line in (b) back into the fault.  d. Leave fault on for 5 cycles, then trip the line in (b) and remove fault.
18.	FLT18-1PH	Single phase fault and sequence like previous
19.	FLT19-3PH	3 phase fault on the Pioneer (531391) to PK Goab (531400) 115kV line, near Pioneer.  a. Apply fault at the Pioneer 115kV bus.  b. Clear fault after 5 cycles by tripping the faulted line.  c. Wait 20 cycles, and then re-close the line in (b) back into the fault.  d. Leave fault on for 5 cycles, then trip the line in (b) and remove fault.
20.	FLT20-1PH	Single phase fault and sequence like previous
21.	FLT21-3PH	3 phase fault on the Holcomb 345kV (531449) to 115kV (531448) transformer, near the 345 kV bus. a. Apply fault at the Holcomb 345kV bus. b. Clear fault after 5 cycles by tripping the faulted transformer.
22.	FLT22-3PH	3 phase fault on the Holcomb (531449) to Setab (531465) 345kV line, near Holcomb.  a. Apply fault at the Holcomb 345kV bus. b. Clear fault after 5 cycles by tripping the faulted line. c. Wait 20 cycles, and then re-close the line in (b) back into the fault. d. Leave fault on for 5 cycles, then trip the line in (b) and remove fault.
23.	FLT23-1PH	Single phase fault and sequence like previous

Cont. No.	Cont. Name	Description
24.	FLT24-3PH	3 phase fault on the Spearville 345kV (531469) to 230kV (539695) transformer, near the 345 kV bus. a. Apply fault at the Spearville 345kV bus. b. Clear fault after 5 cycles by tripping the faulted transformer.
25.	FLT25-3PH	3 phase fault on the Hugoton (531481) to Walkmyr (531405)115kV line, near Hugoton. a. Apply fault at the Hugoton 115kV bus. b. Clear fault after 5 cycles by tripping the faulted line. c. Wait 20 cycles, and then re-close the line in (b) back into the fault. d. Leave fault on for 5 cycles, then trip the line in (b) and remove fault.
26.	FLT26-1PH	Single phase fault and sequence like previous
27.	FLT27-3PH	3 phase fault on the Hugoton (531481) to Grant Tap (531483)115kV line, near Hugoton. a. Apply fault at the Hugoton 115kV bus. b. Clear fault after 5 cycles by tripping the faulted line. c. Wait 20 cycles, and then re-close the line in (b) back into the fault. d. Leave fault on for 5 cycles, then trip the line in (b) and remove fault.
28.	FLT28-1PH	Single phase fault and sequence like previous
29.	FLT29-3PH	3 phase fault on the Kismet (539646) to CMRIVTP (539652) 115kV line, near Kismet. a. Apply fault at the Kismet 115kV bus. b. Clear fault after 5 cycles by tripping the faulted line. c. Wait 20 cycles, and then re-close the line in (b) back into the fault. d. Leave fault on for 5 cycles, then trip the line in (b) and remove fault.
30.	FLT30-1PH	Single phase fault and sequence like previous
31.	FLT31-3PH	3 phase fault on the Kismet (539646) to Cudahy (539659) 115kV line, near Kismet.  a. Apply fault at the Kismet 115kV bus.  b. Clear fault after 5 cycles by tripping the faulted line.  c. Wait 20 cycles, and then re-close the line in (b) back into the fault.  d. Leave fault on for 5 cycles, then trip the line in (b) and remove fault.
32.	FLT32-1PH	Single phase fault and sequence like previous
33.	FLT33-3PH	3 phase fault on the CMRIVTP (539652) to E-Liberty (539672) 115kV line, near CMRIVTP.  a. Apply fault at the CMRIVTP 115kV bus. b. Clear fault after 5 cycles by tripping the faulted line. c. Wait 20 cycles, and then re-close the line in (b) back into the fault. d. Leave fault on for 5 cycles, then trip the line in (b) and remove fault.
34.	FLT34-1PH	Single phase fault and sequence like previous
35.	FLT35-3PH	3 phase fault on the Cudahy (539659) to GEN-2008-079 Tap (573029) 115kV line, near Cudahy. a. Apply fault at the Cudahy 115kV bus. b. Clear fault after 5 cycles by tripping the faulted line. c. Wait 20 cycles, and then re-close the line in (b) back into the fault. d. Leave fault on for 5 cycles, then trip the line in (b) and remove fault.
36.	FLT36-1PH	Single phase fault and sequence like previous

Cont. No.	Cont. Name	Description
37.	FLT37-3PH	3 phase fault on the Medicine Lodge (539673) to Sun City (539697) 115kV line, near Medicine Lodge. a. Apply fault at the Medicine Lodge 115kV bus. b. Clear fault after 5 cycles by tripping the faulted line. c. Wait 20 cycles, and then re-close the line in (b) back into the fault. d. Leave fault on for 5 cycles, then trip the line in (b) and remove fault.
38.	FLT38-1PH	Single phase fault and sequence like previous
39.	FLT39-3PH	3 phase fault on the Mullergren (539679) to South Hays (530582) 230kV line, near Mullergren. a. Apply fault at the Mullergren 230kV bus. b. Clear fault after 5 cycles by tripping the faulted line. c. Wait 20 cycles, and then re-close the line in (b) back into the fault. d. Leave fault on for 5 cycles, then trip the line in (b) and remove fault.
40.	FLT40-1PH	Single phase fault and sequence like previous
41.	FLT41-3PH	3 phase fault on the Mullergren (539679) to Circle (532871) 230kV line, near Mullergren. a. Apply fault at the Mullergren 230kV bus. b. Clear fault after 5 cycles by tripping the faulted line. c. Wait 20 cycles, and then re-close the line in (b) back into the fault. d. Leave fault on for 5 cycles, then trip the line in (b) and remove fault.
42.	FLT42-1PH	Single phase fault and sequence like previous
43.	FLT43-3PH	3 phase fault on the Pratt (539687) to Ninnescah (539648) 115kV line, near Pratt.  a. Apply fault at the Pratt 115kV bus.  b. Clear fault after 5 cycles by tripping the faulted line.  c. Wait 20 cycles, and then re-close the line in (b) back into the fault.  d. Leave fault on for 5 cycles, then trip the line in (b) and remove fault.
44.	FLT44-1PH	Single phase fault and sequence like previous
45.	FLT45-3PH	3 phase fault on the Pratt (539687) to Sawyer (539649) 115kV line, near Pratt.  a. Apply fault at the Pratt 115kV bus.  b. Clear fault after 5 cycles by tripping the faulted line.  c. Wait 20 cycles, and then re-close the line in (b) back into the fault.  d. Leave fault on for 5 cycles, then trip the line in (b) and remove fault.
46.	FLT46-1PH	Single phase fault and sequence like previous
47.	FLT47-3PH	3 phase fault on the Spearville (539695) to Mullergren (539679) 230kV line, near Spearville. a. Apply fault at the Spearville 230kV bus. b. Clear fault after 5 cycles by tripping the faulted line. c. Wait 20 cycles, and then re-close the line in (b) back into the fault. d. Leave fault on for 5 cycles, then trip the line in (b) and remove fault.
48.	FLT48-1PH	Single phase fault and sequence like previous
49.	FLT49-3PH	3 phase fault on the Spearville 230kV (539695) to 115kV (539694) transformer, near the 230 kV bus. a. Apply fault at the Spearville 230kV bus. b. Clear fault after 5 cycles by tripping the faulted transformer.

Cont. No.	Cont. Name	Description
50.	FLT50-3PH	3 phase fault on the GEN-2001-039A (579025) to Fort Dodge (539671) 115kV line, near GEN-2001-039A.  a. Apply fault at the GEN-2001-039A 115kV bus. b. Clear fault after 5 cycles by tripping the faulted line. c. Wait 20 cycles, and then re-close the line in (b) back into the fault. d. Leave fault on for 5 cycles, then trip the line in (b) and remove fault.
51.	FLT51-1PH	Single phase fault and sequence like previous
52.	FLT52-3PH	3 phase fault on the Axtell (640065) to Pauline (640312) 345kV line, near Axtell. a. Apply fault at the Axtell 345kV bus. b. Clear fault after 5 cycles by tripping the faulted line. c. Wait 20 cycles, and then re-close the line in (b) back into the fault. d. Leave fault on for 5 cycles, then trip the line in (b) and remove fault.
53.	FLT53-1PH	Single phase fault and sequence like previous
54.	FLT54-3PH	3 phase fault on the Axtell (640065) to Sweetwater (640374) 345kV line, near Axtell. a. Apply fault at the Axtell 345kV bus. b. Clear fault after 5 cycles by tripping the faulted line. c. Wait 20 cycles, and then re-close the line in (b) back into the fault. d. Leave fault on for 5 cycles, then trip the line in (b) and remove fault.
55.	FLT55-1PH	Single phase fault and sequence like previous

#### 5.2 Further Model Preparation

The base cases contain prior queued projects as shown in Table 7.

The wind generation from the study customer and the previously queued customers were dispatched into the SPP footprint.

Initial simulations were carried out on both base cases and cases with the added generation for a no-disturbance run of 20 seconds to verify the numerical stability of the model. All cases were confirmed to be stable.

**Table 7: Prior Queued Projects Included** 

Project	MW
Montezuma	110
GEN-2001-039A	105
GEN-2002-008	120
GEN-2002-025A	150
GEN-2003-019	250
GEN-2005-012	160
GEN-2006-021	100
GEN-2006-044	80

The projects listed in Table 8 are higher or equally queued projects that are <u>not</u> included in this analysis. If any of these projects come into service, this study will need to be re-performed to determine if any limited capacity is available.

**Table 8: Prior Queued Projects Not Included** 

Project	MW
GEN-2004-014*	155
GEN-2005-012	90
GEN-2006-006*	206
GEN-2006-022*	150
GEN-2006-044	290
GEN-2006-049	400
GEN-2007-038	200

<sup>\*</sup> These projects were included in sensitivity analysis.

## 5.3 Results

Results of the stability analysis are summarized in Table 9. These results are valid for GEN-2008-018 interconnecting with a generation amount of 369 MW with both the Balanced Portfolio Project; Spearville – Post Rock 345kV and Hitchland – Moore County 230kV projects in-service. The results indicate that for all contingencies studied the transmission system remains stable.

**Table 9: Results of Simulated Contingencies** 

Cont. No.	Cont. Name	Description	2011 Summer	2011 Winter
1.	FLT01-3PH	3 phase fault on the Woodward (515375) to Tatonga (515407) 345kV line, near Woodward.	Stable	Stable
2.	FLT02-1PH	Single phase fault and sequence like previous	Stable	Stable
3.	FLT03-3PH	3 phase fault on the Finney (523853) to Hitchland (523097) 345kV line, near Finney.	Stable	Stable
4.	FLT04-1PH	Single phase fault and sequence like previous	Stable	Stable
5.	FLT05-3PH	3 phase fault on one of the Finney (523853) to Holcomb (531449) 345kV lines, near Finney.	Stable	Stable
6.	FLT06-1PH	Single phase fault and sequence like previous	Stable	Stable
7.	FLT07-3PH	3 phase fault on the Finney (523853) to Lamar (599950) 345kV line, near Finney.	Stable	Stable
8.	FLT08-1PH	Single phase fault and sequence like previous	Stable	Stable
9.	FLT09-3PH	3 phase fault on the Knoll (530558) to Post Rock (530584) 230kV line, near Knoll.	Stable	Stable
10.	FLT10-1PH	Single phase fault and sequence like previous	Stable	Stable
11.	FLT11-3PH	3 phase fault on the Knoll (530558) to Smoky Hills (530592) 230kV line, near Knoll.	Stable	Stable
12.	FLT12-1PH	Single phase fault and sequence like previous	Stable	Stable
13.	FLT13-3PH	3 phase fault on the GEN-2007-040 (531000) to Holcomb (531449) 345kV line, near GEN-2007-040.	Stable	Stable
14.	FLT14-1PH	Single phase fault and sequence like previous	Stable	Stable
15.	FLT15-3PH	3 phase fault on the GEN-2007-040 (531000) to Spearville (531469) 345kV line, near GEN-2007-040.	Stable	Stable
16.	FLT16-1PH	Single phase fault and sequence like previous	Stable	Stable
17.	FLT17-3PH	3 phase fault on the Pioneer (531391) to Hickock (531378) 115kV line, near Pioneer.	Stable	Stable
18.	FLT18-1PH	Single phase fault and sequence like previous	Stable	Stable
19.	FLT19-3PH	3 phase fault on the Pioneer (531391) to PK Goab (531400) 115kV line, near Pioneer.	Stable	Stable
20.	FLT20-1PH	Single phase fault and sequence like previous	Stable	Stable
21.	FLT21-3PH	3 phase fault on the Holcomb 345kV (531449) to 115kV (531448) transformer, near the 345 kV bus.	Stable	Stable
22.	FLT22-3PH	3 phase fault on the Holcomb (531449) to Setab (531465) 345kV line, near Holcomb.	Stable	Stable
23.	FLT23-1PH	Single phase fault and sequence like previous	Stable	Stable
24.	FLT24-3PH	3 phase fault on the Spearville 345kV (531469) to 230kV (539695) transformer, near the 345 kV bus.	Stable	Stable

Cont. No.	Cont. Name	Description	2011 Summer	2011 Winter
25.	FLT25-3PH	3 phase fault on the Hugoton (531481) to Walkmyr (531405)115kV line, near Hugoton.	Stable	Stable
26.	FLT26-1PH	Single phase fault and sequence like previous	Stable	Stable
27.	FLT27-3PH	3 phase fault on the Hugoton (531481) to Grant Tap (531483)115kV line, near Hugoton.	Stable	Stable
28.	FLT28-1PH	Single phase fault and sequence like previous	Stable	Stable
29.	FLT29-3PH	3 phase fault on the Kismet (539646) to CMRIVTP (539652) 115kV line, near Kismet.	Stable	Stable
30.	FLT30-1PH	Single phase fault and sequence like previous	Stable	Stable
31.	FLT31-3PH	3 phase fault on the Kismet (539646) to Cudahy (539659) 115kV line, near Kismet.	Stable	Stable
32.	FLT32-1PH	Single phase fault and sequence like previous	Stable	Stable
33.	FLT33-3PH	3 phase fault on the CMRIVTP (539652) to E-Liberty (539672) 115kV line, near CMRIVTP.	Stable	Stable
34.	FLT34-1PH	Single phase fault and sequence like previous	Stable	Stable
35.	FLT35-3PH	3 phase fault on the Cudahy (539659) to GEN-2008-079 Tap (573029) 115kV line, near Cudahy.	Stable	Stable
36.	FLT36-1PH	Single phase fault and sequence like previous	Stable	Stable
37.	FLT37-3PH	3 phase fault on the Medicine Lodge (539673) to Sun City (539697) 115kV line, near Medicine Lodge.	Stable	Stable
38.	FLT38-1PH	Single phase fault and sequence like previous	Stable	Stable
39.	FLT39-3PH	3 phase fault on the Mullergren (539679) to South Hays (530582) 230kV line, near Mullergren.	Stable	Stable
40.	FLT40-1PH	Single phase fault and sequence like previous	Stable	Stable
41.	FLT41-3PH	3 phase fault on the Mullergren (539679) to Circle (532871) 230kV line, near Mullergren.	Stable	Stable
42.	FLT42-1PH	Single phase fault and sequence like previous	Stable	Stable
43.	FLT43-3PH	3 phase fault on the Pratt (539687) to Ninnescah (539648) 115kV line, near Pratt.	Stable	Stable
44.	FLT44-1PH	Single phase fault and sequence like previous	Stable	Stable
45.	FLT45-3PH	3 phase fault on the Pratt (539687) to Sawyer (539649) 115kV line, near Pratt.	Stable	Stable
46.	FLT46-1PH	Single phase fault and sequence like previous	Stable	Stable
47.	FLT47-3PH	3 phase fault on the Spearville (539695) to Mullergren (539679) 230kV line, near Spearville.	Stable	Stable
48.	FLT48-1PH	Single phase fault and sequence like previous	Stable	Stable
49.	FLT49-3PH	3 phase fault on the Spearville 230kV (539695) to 115kV (539694) transformer, near the 230 kV bus.	Stable	Stable

Cont. No.	Cont. Name	Description	2011 Summer	2011 Winter
50.	FLT50-3PH	3 phase fault on the GEN-2001-039A (579025) to Fort Dodge (539671) 115kV line, near GEN-2001-039A.	Stable	Stable
51.	FLT51-1PH	Single phase fault and sequence like previous	Stable	Stable
52.	FLT52-3PH	3 phase fault on the Axtell (640065) to Pauline (640312) 345kV line, near Axtell.	Stable	Stable
53.	FLT53-1PH	Single phase fault and sequence like previous	Stable	Stable
54.	FLT54-3PH	3 phase fault on the Axtell (640065) to Sweetwater (640374) 345kV line, near Axtell.	Stable	Stable
55.	FLT55-1PH	Single phase fault and sequence like previous	Stable	Stable

# 5.4 FERC LVRT Compliance

FERC Order #661A places specific requirements on wind farms through its Low Voltage Ride Through (LVRT) provisions. For Interconnection Agreements signed after December 31, 2006, wind farms shall stay on line for faults at the POI that draw the voltage down at the POI to 0.0 pu.

Three fault contingencies were developed to verify that the wind farm will remain on line when the POI voltage is drawn down to 0.0 pu. These contingencies are shown in Table 10.

**Table 10: LVRT Fault Contingencies** 

Cont. Name	Description
FLT03-3PH	3 phase fault on the Finney (523853) to Hitchland (523097) 345kV line, near Finney. a. Apply fault at the Finney 345kV bus. b. Clear fault after 5 cycles by tripping the faulted line. c. Wait 20 cycles, and then re-close the line in (b) back into the fault. d. Leave fault on for 5 cycles, then trip the line in (b) and remove fault.
FLT05-3PH	3 phase fault on one of the Finney (523853) to Holcomb (531449) 345kV lines, near Finney.  a. Apply fault at the Finney 345kV bus.  b. Clear fault after 5 cycles by tripping the faulted line.  c. Wait 20 cycles, and then re-close the line in (b) back into the fault.  d. Leave fault on for 5 cycles, then trip the line in (b) and remove fault.
FLT07-3PH	3 phase fault on the Finney (523853) to Lamar (599950) 345kV line, near Finney.  a. Apply fault at Finney (599950) 345kV bus.  b. Clear fault after 5 cycles by tripping the faulted line.  c. Wait 20 cycles, and then re-close the line in (b) back into the fault.  d. Leave fault on for 5 cycles, then trip the line in (b) and remove fault.

The project wind farm remained online for the fault contingencies described in this section and for all the fault contingencies described in section 6.2. GEN-2008-018 is found to be in compliance with FERC Order #661A.

### 6.0 Conclusion

<OMITTED TEXT> (Customer) has requested a Limited Operation Impact Study for limited interconnection service of 405 MW of wind generation within the balancing authority of Southwestern Public Service Company (SPS) in Finney County, Kansas, in accordance with the Article 5.9 of the Standard Generation Interconnection Agreement (GIA) in the SPP OATT.

Power flow analysis showed that the Customer's wind facility can interconnect 369 MW of wind generation with Balanced Portfolio Project: Spearville – Post Rock 345kV, and Hitchland – Moore County 230kV projects in-service.

The stability analysis results of this study show that with the above upgrades the wind generation facility and the transmission system remain stable for all contingencies studied. Also, GEN-2008-018 is found to be in compliance with FERC Order #661A.

The projects listed in Table 8 are higher or equally queued projects that are not included in this analysis. If any of these projects come into service, this study will need to be re-performed to determine if any limited capacity is available.

The estimates do not include any costs associated with the deliverability of the energy to final customers. These costs are determined by separate studies if the Customer requests transmission service through Southwest Power Pool's OASIS. It should be noted that the models used for simulation do not contain all SPP transmission service.